

South Coast EVS - Ontario
 2020 SOUTH BAKER AVE
 Ontario, CA 91761
 service@southcoastevs.net
 909-930-2278



Estimate **SO-1048**
Date: **12/1/2023**

Bill To
 CITY OF REDONDO BEACH

 P: 310-318-0623

Remit Payment To
 Primary
 2020 SOUTH BAKER AVE
 Ontario, CA 91761

Service Order		Purchase Order	Authorizer	
SO-1048				
Item	Description	Quantity	Rate	Amount
Complaint: REAR TRAFFIC ADVISOR				
Cause: Customer request				
Labor	Recommended Correction: Electrical System / Lighting / REAR TRAFFIC ADVISOR	2.00000	\$170.00	\$340.00
Parts	6-LT FRONT LOAD LINEAR LED T/A	1	\$1,218.02436	\$1,218.02
Parts	TACTL5 CONTROL HEAD	1	\$500.01	\$500.01
Complaint: REAR TAILLIGHT HOUSING				
Cause: Customer request				
Labor	Recommended Correction: Electrical System / Lighting / REAR TAILLIGHT HOUSING	8.00000	\$170.00	\$1,360.00
Parts	600 LIN.SUPER-LED FLASH RED	2	\$232.00464	\$464.01
Parts	600 LED TURN AMBER	2	\$171.00342	\$342.01
Parts	600 LED BRAKE/TAIL/TURN RED	2	\$233.00466	\$466.01
Parts	600 LED BACK-UP LIGHT	2	\$171.00342	\$342.01
Complaint: REAR BEACONS				
Cause: Customer request				
Labor	Recommended Correction: Electrical System / Lighting / REAR BEACONS	2.00000	\$170.00	\$340.00
Parts	MICRO FREEDOM LT HEAD RED/CLR	2	\$917.01834	\$1,834.04
Complaint: SIDE LIGHTING				
Cause: Customer request				
Labor	Recommended Correction: Electrical System / Lighting / SIDE LIGHTING	16.00000	\$170.00	\$2,720.00

Item	Description	Quantity	Rate	Amount
Parts	600 LIN.SUPER-LED FLASH RED -- REPLACES SIDE LIGHTS ON TRAILER	6	\$232.00464	\$1,392.03
Parts	OPT. FLANGE, 64/6E/600 SERIES	6	\$28.00056	\$168.00
Parts	600 LIN. SUPER-LED FLASH RED -- REPLACES 2 ABOVE FRONT WHEEL WELL & 2 SIDE OF FRONT BUMPER	4	\$214.00428	\$856.02

Complaint: FRONT LIGHTING**Cause:** Customer request

Labor	Recommended Correction: Electrical System / Lighting / FRONT LIGHTING	4.00000	\$170.00	\$680.00
Parts	600 LIN. SUPER-LED FLASH RED -- REPLACES LIGHTS IN HEADLIGHT BEZEL	2	\$232.00464	\$464.01
Parts	600 LED TURN AMBER -- REPLACES LIGHTS IN HEADLIGHT BEZEL	2	\$171.00342	\$342.01

Complaint: FORWARD FACING LIGHTBAR**Cause:** Customer request

Labor	Recommended Correction: Electrical System / Lighting / FORWARD FACING LIGHTBAR	15.00000	\$170.00	\$2,550.00
Parts	81" FREEDOM IV WCX, NFPA LIGHTBAR	1	\$4,908.09816	\$4,908.10
Parts	WCX NFPA FREEDOM IV CONTROL PT	1	\$269.00538	\$269.01
Parts	FREEDOM IV + 1 LONG 12LED RED	10	\$283.00566	\$2,830.06
Parts	MOUNT KIT 20 SLIDE BOLT (3)	1	\$113.00226	\$113.00

Complaint: SIDE FACING LIGHTBARS**Cause:** Customer request

Labor	Recommended Correction: Electrical System / Lighting / SIDE FACING LIGHTBARS	8.00000	\$170.00	\$1,360.00
Parts	21.5" MINI FREEDOM IV DYAD SERIES RED LED (1 DRIVER, 1 PASSENGER)	2	\$1,332.02664	\$2,664.05
Parts	FREEDOM IV + 1 LONG 12LED RED	4	\$283.00566	\$1,132.02
Parts	CORE CONTROL POINT	2	\$215.0043	\$430.01

Shop Supplies				\$100.00
---------------	--	--	--	----------

Unit: VIN: ADDTHISLATER
2001ALF
Chassis: 0 Miles

Subtotal	\$30,184.43
CA 8.75% (8.75% of \$20,834.43)	\$1,823.01
Total	\$32,007.44

*: Core charges not included in total. You will be charged for any core that is not in returnable condition. This charge may be applied on a

separate invoice.

The details and the estimate for the repairs provided above are based on our first inspection and do not constitute a guarantee that no further work or parts will be required. The estimate is not a guarantee of the final price of the repairs. The total bill of work and final price will be as per the details available on completion of the repairs. In the event additional issues are identified that are not covered by this estimate, a separate invoice may be issued. Other terms and conditions as applicable. If you authorize us to perform the above repairs, either verbally or in writing, you agree to pay in full for the work performed and parts required.

Customer Signature: _____

Printed Name: _____ Date: _____